

API-653 In-Service, Internal Inspection Report

Prepared for:

Northeast Generation Services
South Meadow Jet Station
Hartford, CT

Subject Tank:

Tank 6
Jet-A Tank



Prepared by:

InTANK

InTANK, LLC
Project No. NU-2009-1 Rev. 00

InTANK, LLC
5443 Trail Ride Ct
Moseley, VA 23120
www.intank.com

API-653 In-Service, Internal Inspection Report

Northeast Generation Services South Meadow Jet Station

Tank 6

Inspection Date:

August 10 – 21, 2009

It is recommended that this document,
containing valuable historical information,
be retained for the lifetime of the tank.

Michael O'Connell
API-653 Certified Inspector, Certificate # 24021

InTANK

Executive Summary

During the week of August 17, 2009, InTANK, LLC completed an inspection on Tank 6, the main Jet Fuel storage tank located at the Connecticut Resources Recovery Authority's (CRRA), South Meadow facility in Hartford, CT, operated by Northeast Generation Services Company (NGS). The purpose of the inspection was to assist in the evaluation of external, chime¹ / bottom plate corrosion that was identified during a recent external inspection. The most severe corrosion was found on the chime along a 7-foot section on the west side of the tank.

An external, under tank inspection was completed by hand-excavating the tank foundation in the area of the worst chime corrosion. The foundation was removed to a distance of approximately 6" under the tank shell. The external surface of the tank bottom was then cleaned by hand using scrapers, files and wire brushes.

The underside of the tank bottom was too rough to perform a complete UT scan, but thickness readings in discrete locations were obtained using manual ultrasonics. The thickness readings ranged from 0.136" to 0.210" indicating significant corrosion in this area of the tank bottom. The most severe metal loss was found closest to the tank perimeter.

The main focus of the inspection was an internal, robotic inspection of the tank bottom. Special attention was made to the tank perimeter in the area of the external chime corrosion on the west side of the tank.

As with the external inspection, the robotic inspection also found significant external (underside) corrosion on the west perimeter of the tank. The minimum thickness found by the robotic system was 0.159".

Based on the available data and using both long-term and short term corrosion rates, it is our opinion that the remaining service life of Tank 6 is less than three-years.

Given the difficulty in predicting exact corrosion rates and given the age of Tank 6, it is our recommendation that the tank be removed from service within 2 years from this date (removed from service no later than August 2011). The tank could be inspected and repaired at that time if desired.

The tank should also be monitored on a frequent basis for signs of leaking or other distress. It is also recommended that the amount of oil stored in the tank be kept to the minimum needed for normal plant operation until the tank can be removed from service.

¹ The "chime" is the portion of the tank bottom that extends outward from under the tank shell. This is also known as the "sketch plate extension".

Tank 6

All Field Data Can Be Found In the Attached Appendices

INTRODUCTION AND HISTORY

During the week of August 17, 2009, InTANK, LLC completed an inspection on Tank 6, the main Jet Fuel storage tank located at the Connecticut Resources Recovery Authority's (CRRA), South Meadow facility in Hartford, CT, operated by Northeast Generation Services Company (NGS). The purpose of the inspection was to assist in the evaluation of external, chime² / bottom plate corrosion that was identified during a recent external inspection. The most severe corrosion was found on the chime along a 7-foot section on the west side of the tank.

History

In 2004, InTANK Services, Inc.³ completed a robotic internal inspection of Tank 6. The 2004 inspection found no significant corrosion in the tank bottom.

In 2009, an external inspection completed by a third party observed significant corrosion on the tank bottom chime. The most severe corrosion appeared to be on the west side of the tank (see photos in Appendix B).

In reviewing the 2004 InTANK Services report, it appears that the internal perimeter along the west side of the tank was not inspected.

Since the most severe chime corrosion was reported on the west side of the tank and no data from this region of the tank was available from the 2004 inspection, NGS requested that this additional inspection be completed.

² The "chime" is the portion of the tank bottom that extends outward from under the tank shell. This is also known as the "sketch plate extension".

³ InTANK Services, Inc, is not affiliated with InTANK, LLC

INFORMATION AND DATA

Type of Inspection:	API-653 In-Service, Internal
Test Methods Used:	Visual, Ultrasonic Thickness Survey, Dye Penetrant (PT)
Tank Manufacturer:	CB&I
Year Built:	1946
Code Built To:	API-12C
Diameter:	140'
Height:	48'
Foundation:	Soil
Product Stored:	Jet-A
Specific Gravity:	0.85
Shell Construction:	Butt Welded
Bottom Plate Thickness:	0.250"
Sketch Plate Thickness:	0.3125"
Joint Efficiency:	0.85 (assumed)
Plate Material Specification:	A36 (assumed)

INSPECTION PROCEDURE

The inspection covered by this report consisted of three components; (1) an external, under tank inspection of the area around the most severe corrosion, (2) a dye penetrant (PT) inspection of the welds in the affected area and (3) a robotic internal inspection with special attention to the area not inspected in 2004.

EXTERNAL, UNDERTANK INSPECTION

The external, under tank inspection was completed by hand-excavating the tank foundation in the area of the worst chime corrosion. The foundation was removed to a distance of approximately 6" under the tank shell.

The external surface of the tank bottom was then cleaned by hand using scrapers, files and wire brushes. The underside of the tank bottom was too rough to perform a complete UT scan, but thickness readings in discrete locations were obtained using manual ultrasonics.

The thickness readings ranged from 0.136" to 0.210" in the nominal 5/16" (0.3125") plate indicating significant corrosion in this area of the tank bottom. The most severe metal loss was found closest to the tank perimeter.

Please note that while conditions were not optimal to collect thickness data, we are confident in the data collected.

All of the thickness readings collected from under the tank can be found in Appendix A.

DYE PENETRANT (PT) INSPECTION

Given the severity of the corrosion seen on the chime and lower tank shell, it was decided to complete a PT inspection of approximately 15' of the external corner weld and a 12" section of the nearest vertical weld on the shell.

The results of the PT inspection were negative with no linear indications seen. At this time, it appears that the metal loss to the external corner weld has not caused any distortion or cracking.

Photos documenting the PT inspection can be found in Appendix B.

NOTE: The dye penetrant (PT) inspection was done as an improved visual inspection technique only. It was not conducted as a code inspection and it is not a required component to an API-653 internal inspection.

ROBOTIC INTERNAL INSPECTION

The main focus of the inspection was an internal, robotic inspection of the tank bottom. Special attention was made to the internal tank perimeter in the area of the external chime corrosion on the west side of the tank.

As with the external inspection, the robotic inspection also found significant external (underside) corrosion on the west perimeter of the tank. The minimum thickness found by the robotic system was 0.159" in the nominal 5/16" (0.3125") plate⁴.

Outside of the west perimeter of the tank, additional corrosion was found along the tank perimeter, but the remaining thickness found ranged from 0.228" to 0.312", indicating

⁴ The perimeter or "sketch" plates are nominally 5/16" (0.3125") thick; the bottom plates away from the perimeter are nominal 1/4" (0.250") plate.

less severe corrosion than the west perimeter. The average thickness of the sketch plates away from the west perimeter was 0.281”.

Other than the perimeter corrosion noted, the remainder of the tank bottom showed no signs of significant metal loss and the thickness readings appeared consistent with the readings from the 2004 robotic inspection.

A summary of the robotic inspection is presented below. All of the thickness data can be found in Appendix A. **(NOTE: The data shown in Appendix A represents the minimum thickness obtained from a 12” or 24” scan contained within each grid location).**

TANK PERIMETER (Sketch Plates)

Number of Runs:	243
Nominal Thickness:	0.312”
Average Thickness:	0.269”
Minimum Thickness:	0.159”
Standard Deviation:	0.030”

TANK BOTTOM (Bottom Plates)

Number of Runs:	182
Nominal Thickness:	0.250”
Average Thickness:	0.251”
Minimum Thickness:	0.220”
Standard Deviation:	0.010”

EXTREME VALUE ANALYSIS

As part of this evaluation, an Extreme Value Analysis (EVA) was completed on the thickness data collected from the tank’s sketch plates.

EVA is a recognized statistical method for determining the statistical minimum from a sample of data collected. EVA is routinely used to determine theoretical minimums from thickness data collected from tanks, piping and other structures.

Based on the data collected from the perimeter of Tank 6, our EVA predicted that the minimum thickness in the sketch plates would equate to 0.135” using a confidence factor of 95.2%.

Please note that the EVA minimum of 0.135” is almost identical to the minimum thickness of 0.136” found during the manual, under tank inspection.

While not definitive, the agreement between the actual minimum and the statistical minimum is a good indication of the accuracy of the overall results from this inspection.

The EVA data plot can be found in Appendix C of this report.

CORROSION RATE AND REMAINING LIFE CALCULATIONS

Based on the data collected from this inspection, we have made the following corrosion rate and remaining life calculations for the tank sketch plates (the bottom plates show no significant corrosion at this time):

Long Term Corrosion Rate $0.312'' - 0.136'' / 2009 - 1945 = 0.00275''/\text{yr}$

Short Term Corrosion Rate $0.269'' - 0.136'' / 2009 - 2004 = 0.0266''/\text{yr}$

Average Corrosion Rate $0.0266'' + 0.00275 / 2 = 0.01468''/\text{yr}$

Remaining Service Life⁵ $0.136'' - 0.100'' / 0.01468''/\text{yr} = 2.45 \text{ years}$

Using the average corrosion rate shown above, it can be calculated that Tank 6 has a remaining service life as defined in API-653 of 2.45 years.

CONCLUSION AND RECOMMENDATION

Based on the findings from our inspection, it appears that Tank 6 is not in imminent danger of failure, but the tank has experienced significant corrosion and is reaching the end of its service life.

Given the difficulty in predicting exact corrosion rates and given the age of Tank 6, it is our recommendation that the tank be removed from service within 2 years from this date (removed from service no later than August 2011). The tank could be and inspected and repaired at that time if so desired.

In addition, we make the following discretionary recommendations:


1. The tank should be monitored on a frequent basis for signs of leaking or other distress.
2. The amount of oil stored in the tank should be kept to the minimum needed for normal plant operation until the tank can be removed from service.

⁵ As defined in API-653

Appendix A – Field Data

The following drawings show the thickness and other data obtained during the internal inspection.

InTANK, LLC
Northeast Generation Services
Tank 6
API-653 In-Service, Internal Inspection Report



InTANK, LLC
 Northeast Generation Services
 Tank 6
 API-653 In-Service, Internal Inspection Report

Northeast Utilities Tank No. 6						
Nominal 1/4" Bottom Plates						
Grid 4	266	260		Grid 11	248	221
	268	260			258	243
	278	244			252	259
	264	257			251	249
	254					
Grid 5	251	245		Grid 24	238	255
	262	248			244	249
	264				242	
	254				252	
	246					
				Grid 25	260	266
Grid 6	260	254			264	254
	248	224			258	252
	220	239			252	
	262	240				
				Grid 26	243	251
Grid 7	266	259			239	249
	259	244			257	
	254				255	
	263					
	270			Grid 27	258	248
					260	249
Grid 8	260	255			254	
	254	248			244	
	262	260				
	249	238		Grid 28	253	245
					251	251
Grid 9	268	280			248	251
	264	282			247	
	278	287				
	254	263		Grid 29	248	237
	248	258			248	239
					254	250
					239	255

InTANK, LLC
 Northeast Generation Services
 Tank 6
 API-653 In-Service, Internal Inspection Report

Northeast Utilities Tank No. 6						
Nominal 1/4" Bottom Plates						
Grid 30	249	250		Grid 50	241	250
	259	248			243	249
	255	255			251	246
	254	250			254	243
					255	
Grid 31	234	250				
	238	245		Grid 51	243	255
	252	247			246	253
	252	246			255	253
	254					
	246			Grid 52	249	257
					250	252
Grid 44	245	248			249	250
	245	262				
	244			Grid 53	228	224
	260				234	241
					240	238
Grid 45	244	248			240	236
	256	250			257	
	258	255			255	
	252	256				
	249	250				
Grid 49	254	262				
	251	253				
	254	255				
	253	257				
	260	258				

InTANK, LLC
 Northeast Generation Services
 Tank 6
 API-653 In-Service, Internal Inspection Report


Northeast Utilities Tank No. 6							
Nominal 5/16" Sketch Plates							
Grid 1	229	241	223	Grid 12	262	255	251
	240	250	221		248	258	249
	258	220	218		244	264	241
	216	248	163		238	255	239
	220	260	229		240	250	242
	244	258	232				
	238	252	208	Grid 14	280	269	
	184	179	159		259	287	
					279	301	
Grid 2	226	292	219		289	290	
	248	251	220		287	290	
	248	244	238				
	242	229	240	Grid 21	280	281	303
	245	216	222		310	280	300
	224	227	219		285	293	
	234	244	230		290	301	
Grid 3	266	274	218	Grid 22	312	304	
	280	259	216		300	288	
	264	301	222		300	293	
	245	249	240		289	300	
	220	221	239				
	224	240	240	Grid 23	279	308	
					301	307	
Grid 9	268	280			288		
	264	282			284		
	278	287					
	254	263		Grid 34	288	306	
	248	258			294	279	
					295	301	
Grid 10	257	232	228		304	306	
	255	264	237			293	
	238	268	255				
				Grid 35	N/A		

InTANK, LLC
 Northeast Generation Services
 Tank 6
 API-653 In-Service, Internal Inspection Report

Northeast Utilities Tank No. 6					
Nominal 5/16" Sketch Plates					
Grid 36	300	303	Grid 54	290	285
	285	284		292	281
	290	281		300	
		278		301	
		281		284	
Grid 37	296	297	Grid 55	298	244
	294	294		300	228
	288	254		260	275
	288	260		254	301
	248	262		240	289
	288			231	231
			Grid 56	300	276
Grid 46	280	294		274	303
	285	290		279	301
	274	285		280	
	272	285			
	281	291	Grid 57	295	306
	295	292		293	298
				298	304
Grid 47	300	288		296	301
	301	288		301	293
	289	300			
	290	301	Grid 64	300	289
	284	293		297	289
				294	294
Grid 48	290	251		296	303
	284	290		301	
	270	300			
	274		Grid 65	301	303
	268			287	304
				286	303
				288	301

InTANK, LLC
 Northeast Generation Services
 Tank 6
 API-653 In-Service, Internal Inspection Report

Northeast Generation Services
 Jet-A Tank
 Tank 6
 10-6-08
 InTANK Project NU-2009-01



External UT on Tank Bottom
 in Area of West Chime Corrosion
 Area Excivated Under Shell

(NOTE: Plan View -- Location of
 Readings is Approximate)

Appendix B Photographs (External)

Tank 6

Northeast Generation Services
Hartford, CT

InTANK, LLC
Northeast Generation Services
Tank 6
API-653 In-Service, Internal Inspection Report



Photo 1: General View of Tank 6



Photo 2: Area of Most Severe Chime Corrosion (west side of tank)

InTANK, LLC
Northeast Generation Services
Tank 6
API-653 In-Service, Internal Inspection Report



Photo 3: Results of Dye Penetrant Examination (Note absence of linear indications)



Photo 4: Close-up View of Dye Penetrant Inspection

Appendix C

Extreme Value Analysis (EVA) Plot

InTANK, LLC
 Northeast Generation Services
 Tank 6
 API-653 In-Service, Internal Inspection Report

