



- NOTES:**
- INDICATES LIMITS OF PARTIAL DEPTH CONCRETE REPAIR AREA.
 - INDICATES LIMITS OF TRANSITION AREA FROM NEW MSW CONCRETE OVERLAY TO EXISTING MSW CONC. SLAB.

**CONNECTICUT
RESOURCES
RECOVERY
AUTHORITY**
TEL. NO. (860)-757-7700
FAX. NO. (860)-757-7742

A&E FIRM
URS
URS CORPORATION AES
500 ENTERPRISE DRIVE
ROCKY HILL, CT. 06067
1-(860)-529-8882

A&E SEAL

THE INFORMATION CONTAINED IN THIS SET OF DOCUMENTS IS PROPRIETARY BY NATURE. ANY USE, DISCLOSURE OTHER THAN THAT WHICH RELATES TO COVANTA MID-CONN., INC. IS STRICTLY PROHIBITED.

REVISIONS

NUMBER	DATE	REMARKS

**MID-CONNECTICUT
PROJECT
MSW FLOOR
REPAIR**

MAXIM ROAD
HARTFORD, CT.

PROJECT NO: 36937394

DRAWN BY: MMM

CHECKED BY: PJG

DATE: 10/24/07

CADD FILE: S004.DWG

**MSW
FLOOR REPAIR
PLAN
(STAGE III & IV)**

S-004

1 MSW FLOOR REPAIR PLAN (STAGE III & IV)
S-004 SCALE: 1" = 10'

